

REPORT of SURVEY for REPAIRS.

19838

No. 942 Survey held at London Date 31st July 1855
on the Bark Cybele Master P. Cruller
Tonnage 334 Built at Miramichi When built 1841
By whom built _____ Owners Colling
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Limetula Ship way & afloat in West India Dock

Last Survey, No. 17909 Port London Classed Blank

REPAIRS

At present time with a view to reclassing upon the
dipthong - Specially opened in accordance with rule
Section 16.3. and the frame timbers where thus exposed
found to be in very sound & wholesome condition
The wales & upper work, having been brightened
and a few trenails driven out - the latter were found
sound but indifferently formed - The Topsides proved
to be considerably defective in many places in connect-
ion with the trenails, likewise the sheer strakes &
Wales in a less degree the vessel's position afloat -
preventing a general & searching examination -
under the facilities at the time

Extract to
Surveyor's Department
3.1.59

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

Under the above circumstances the Owner
has withdrawn the order for survey - and on the
vessel's return from her intended voyage - He will decide
upon his course respecting her repairs &c.

The Amount of Fee.....£ : : is received by me, Thomas Alexander
Special..... 1 : 1 : - 11/8/55

Certificate (if required) : :

Committee's Minute 10th August 1855

Character assigned Deferred

Record duty of Survey



© 2019

Lloyd's Register
Foundation

LON636-0134