

ANNUAL SURVEYS.

19950

No. 169 Survey held at London Date Oct^r 1st 1855
 on the Ship "Ferozepore" Master J. Watson
 Tonnage 497 Built at Newcastle When built 1846
 By whom built _____ Owners Henderson
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Princess' Dry Dock

Last Survey, No. 19191 Port of London Classed 12A.1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> When put on <u>1834</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

Now done, the yellow metal sheathing patched, and iron hanging knee to the upper deck renewed on the port side - She now appears fit in my opinion to remain as classed A.1.

Committee's Minute 5th October 1855

Character assigned

12A.1P. Maymouth

Certificate (if required)

No. 339 Survey held at London Date Oct^r 1st 1855
 on the Barge "Alexandrina" Master Jas Mason
 Tonnage 294 Built at Aberdeen When built 1848
 By whom built _____ Owners Falconer
 Port belonging to London Destined Voyage St Helena
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 17824 Port of London Classed GA.1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

Now done, the bottom Caulked and resheathed with yellow metal on felt; the Fore Mast renewed - She now appears fit in my opinion to remain as classed GA.1.

Committee's Minute 5th October 1855

Character assigned

GA.1recd YMS

© 2019

Lloyd's Register Foundation

Certificate (if required)