

20021

REPORT of SURVEY for REPAIRS.

No. ✓ Survey held at London Date 1st March 1855
on the Bark Anne Master _____
Tonnage 251 Built at Prince Ed^d Island When built 1854
By whom built H. Welsh Owners M. Welsh
Port belonging to Port Ed^d Island Destined Voyage _____
If Surveyed Afloat or in Dry Dock in Surrey Canal afloat

Last Survey, No. None Port _____ Classed _____

REPAIRS - Having agreeable to the special request of the Owner of this vessel attended on board and proposed out the Iron Rines & fastenings also two additional Deck Beams required. Listing in Ceiling to be cut out all as stipulated by the Rules before classification

The above being for the purpose of enabling the owner to decide upon selling her classed or otherwise

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
anksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

I have subsequently learned that the owner has left & indefinitely deferred entering upon classification
Thomas Alexander

The Amount of Fee.....£ : : is received by me,

Special..... / : / : - H

Certificate (if required) : : -

Committee's Minute 185

Character assigned



© 2019

Lloyd's Register
Foundation