

20171

REPORT of SURVEY for REPAIRS.*change of owners*

No. 96 Survey held at London Date 7th Feb^y 1856
 on the Barge "Viceroy" Master Garbutt
 Tonnage 667 Built at Nova Scotia When built 1849
 By whom built _____ Owners Thomas D Hopper
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat, East India Dock

Last Survey, No. 18318 Port London Classed 4 A 1
 Coats & 2 33 53-4 Feb 53

REPAIRS**Present Condition of the**

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Good</u> When put on <u>1853</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. firm & good

This vessel appears to be in a good and efficient state of repair and is eligible in our opinion to remain as classed A 1

The Amount of Fee.....£ 1 : - : - is received by me,

Special..... : : W. G. L. L.Certificate (if required) : : Thos. M. Wain
Richard TothellCommittee's Minute 22nd February 1856Character assigned A 1

© 2019

Lloyd's Register
Foundation

LON636-0466