

20191

REPORT of SURVEY for REPAIRS.

Change of Owners

No. *395* Survey held at *London* Date *February 23rd* 185*6*
 on the *Brig "Selistria"* Master *J. H. Trapp*
 Tonnage *224* Built at *Prince E^d Island* When built *1854*
 By whom built _____ Owners *Trapp*
 Port belonging to *London* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *London Dock*

Last Survey, No. *749* Port *Ipwich* Classed *4 A 1*
55

REPAIRS

*Bills have been produced, showing that the bottom was
 Caulked and sheathed with Zinc in September 1853.*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<i>Zinc</i>	Standing & Running Rigging
Plank (Bottom) and Counter	<i>Copper</i> When put on <i>1853</i>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. *Good where examined*

*She now appears in good and efficient Condition, fit in
 my opinion to remain as classed 4 A 1. B. W. W. auth*

The Amount of Fee.....£ *1* : : is received by me,

Special..... : : }

Certificate (if required) : *5* : - }

Committee's Minute *4th March* 185*6*

Character assigned *4 A 1*
Recorded
[Signature]



© 2019

Lloyd's Register
 Foundation

LON636-0486