

REPORT of SURVEY for REPAIRS.

Change of Owners

No. ⁴⁴⁸ Survey held at London Date 21st May 1856
on the Brig "Christiana Carnell" Master Brockenhire
Tonnage 222 Built at Southampton When built 1830
213
By whom built _____ Owners Brockenhire
Port belonging to London Destined Voyage Buenos Ayres
If Surveyed Afloat or in Dry Dock St. Katherine's Dock

Last Survey, No. 16607 Port London Classed 12 A 1
57

REPAIRS

Bills have been produced which showed that the keel was caulked from the keel to the waterway beam and about the deck framing; the bottom sheathed with Yellow Metal on Telt at the Mauritius in April 1853. -

The keel was partly laden when seen by us. -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter	Copper on Telt When put on 1853	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good
She appears in good Condition, fit in our opinion to remain as classed 12 A 1.

The Amount of Fee.....£ 1 : - : - is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 3rd June 1856

Character assigned 12 A 1



© 2019

Lloyd's Register Foundation

LOW634-0060