

20404

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 673 Survey held at London Date 11th June to 19th 1856
on the Bk "Commodore" Master

Tonnage 203 Built at Newport When built 1835

By whom built Owners Robinson & Co

Port belonging to London Destined Voyage

If Surveyed Afloat or in Dry Dock on the Hard Mill Wall

Last Survey, No. 19245 Port London Classed 2nd M. 1. S.S. 52

REPAIRS On examination found some of the Treenails and some of the Ceiling very defective, also the Caulking of Bottom very slack. Left Notice Card recommending the defective Ceiling and Treenails to be renewed also Yellow Metal sheathing to be stripped off, and Bottom caulked, and all the defects pointed out to be efficiently repaired before she is reported to the Committee to be claped in the Register Book.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The owners have declined repairing the above named defects. We therefore recommend that her character be expunged.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 27th June 1856

Character assigned Expunged Character
Noted to owner
Charged £1.1
S. 27 June

H. Boulds
B. A



© 2019

Lloyd's Register
Foundation

LOW 637-0118