

20543

REPORT of SURVEY for REPAIRS.

No. 162 Survey held at London Date 22nd August 1856
on the Schooner "Diamond" Master Coker
Tonnage 94 Built at Stonehouse When built 1815
By whom built _____ Owners Corry
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Aground on Fernies Ways

Last Survey, No. 445 Port Penzance Classed PS. 48 - 54
omitted -

REPAIRS

On examining this vessel found the walls much piced also some planks below started at the butts; the caulking of the bottoms bad and the midship lengths of Waterway on each side very defective.

Having pointed out the above defects to the Captain he informed me that the owner had determined not to spend any money on the vessel and wished to sell her as she was.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

In her present state we are of opinion that this vessel is not eligible for any character

Thos. McWawn

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required)

H. J. Boulds

Committee's Minute 26th August 1856

Character assigned

Charge £ 2.2.0

Brokers Hooper & Baker

© 2019

Lloyd's Register Foundation

Low 634-0243