

20600

REPORT of SURVEY for REPAIRS.

No. 30 Survey held at London Date Sept 23rd to 23rd 1856
on the Barge "Palm" Master H. Bishop
Tonnage 272 Built at Sunderland When built 1849
By whom built Garraway Owners Garraway
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Lim. Rln Ship & West India Dock

Revised

Last Survey, No. 20002 Port London Classed 10 A 1
55

REPAIRS

Present Condition of the

| | | |
|--|--|--|
| Decks <u>Good</u> | Treenails <u> </u> | Windlass and Capstan <u> </u> |
| Waterways <u>Good</u> | Breasthooks and Stemson <u> </u> | Pumps <u> </u> |
| Comings <u>Good</u> | Transoms, Pointers, and Crutches <u> </u> | Boats <u> </u> |
| Upper Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame <u> </u> | Masts, Yards, &c. <u>Good and</u> |
| Lower Deck Beams & Fastenings <u>where seen</u> | Keelsons <u>Good where</u> | Sails <u>sufft</u> |
| Planksheers <u> </u> | Clamps and Shelves <u>seen</u> | Anchors No. of <u> </u> |
| Sheerstrakes <u>Caulked</u> | Ceiling <u> </u> | Cables <u> </u> |
| Topsides <u> </u> | Rudder <u> </u> | Hawsers and Warps <u> </u> |
| Wales <u> </u> | Copper <u> </u> | Standing & Running Rigging <u> </u> |
| Plank (Bottom) and Counter <u> </u> | When put on <u>1833</u> | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

We sent a Notice Card recommending the hindship shifts of deck each side next the waterway to be renewed, the seam being very open on the lower side and liable to leak. The recommendation has not been attended to, we are therefore of opinion, that her class should be suspended until the waterway seam is made efficient.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 26th September 1856
30th

Character assigned Deferred

B. Wainmanth
Wm. Davidson

2019
Lloyd's Register
Foundation
Lon 634 - 0296