

21074

REPORT of SURVEY for REPAIRS.

No. 106 on the Ship "Suffolk" Survey held at London Date May 12th 1857
 Master J. Martin
 Tonnage 976 Built at Northam When built 1857
 By whom built _____ Owners Wigram & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock East India DOCK

Last Survey, No. 900 Port Southampton Classed 13 A. 1.

REPAIRS

The following stores have now been supplied
 Viz: 1 Iron Stock ironman's Anchor 29 1/2 Cwt
 1 do Rogers' do 32 1/2
 1 do Comman 39
 1 do Stream do (Rogers') 10
 2 do Ridges 5 1/4
 300 fathoms of 1 3/4 Chain cable
 90 do Stream do
 90 fathoms 9 1/2 Hawser
 90 do 6" Warp

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. M.</u> When put on <u>1857</u>	Standing & Running Rigging
Plank (Bottom) and Counter	on felt	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now supplied with a sufficiency of stores, and in my opinion should be classed 13 A. 1.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 28th May 1857

Character assigned 13 A. 1.



© 2019

Lloyd's Register
Foundation

LON 638-0270