

REPORT of SURVEY for REPAIRS.

21077

Rev 25/8/87

No. 64 Survey held at London Date 30th April 1857
 on the Ship "Saladin" Master J. Baillie
 Tonnage 172 Built at Sunderland When built 1851
 By whom built P. S. C. Owners Henderson
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Princes Dock

Last Survey, No. 20213 Port London Classed 13 A 1.

REPAIRS Now done in consequence of a leak viz: - The yellow metal sheathing stripped off from the ten to the twelve feet mark. also the face piece to stem and gripe. removed and one open hole found. Bottom caulked in way of removed sheathing. hole plugged up and face piece refitted and fastened. yellow metal renewed upon side.

Present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>u</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>u</u>
Comings <u>u</u>	Transoms, Pointers, and Crutches <u>u</u>	Boats <u>3 - u</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>seen</u>	Masts, Yards, &c. <u>u</u>
Lower Deck Beams & Fastenings <u>u</u>	Keelsons <u>good</u>	Sails <u>2 good suits</u>
Planksheers <u>good</u>	Clamps and Shelves <u>u</u>	Anchors No. of <u>B.B. 15. 2K</u>
Sheerstrakes <u>u</u>	Ceiling <u>u</u>	Cables <u>good and sufficient</u>
Topsides <u>u</u>	Rudder <u>u</u>	Hawsers and Warps <u>u</u>
Wales <u>u</u>	Copper <u>Y. M. on</u> When put on <u>1856</u>	Standing & Running Rigging <u>u</u>
Plank (Bottom) and Counter <u>good where seen</u>	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>	

General Observations and Opinion,

This vessel is now in good and efficient condition and in our opinion eligible to remain as Classed 13 A 1.

The Amount of Fee.....£ _____ is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 25th May 1857

Character assigned 13 A 1

H. J. Boulders.

J. A. Martin



Lloyd's Register Foundation

LON 638-0273