

21084

REPORT of SURVEY for REPAIRS.

No. 4 Survey held at London Date March 28/4/57 1857
on the "Br McConnell" Master
Tonnage 573 Built at New Brunswick When built 1845
By whom built Owners Sangley & Co
Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock West India & Princes Dry dock
1353/4B 3/2048 Drp 50

Last Survey, No. 18197 Port London Classed Omitted

REPAIRS

An order to survey this ship was lodged at the office on the 27th Feb. The owners to have information afterwards when put into dry dock. When visited in the West India Dock the fine sheathing was found to be much wrinkled and when seen in Princes dock the surveyor was told that the owners declined having her surveyed. She was seen afterwards by Mr Couchman in the West India dock found much in want of repair for any class.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>apparently broken at the bilge</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Until submitted to survey and repaired we are of opinion she is unfit for any class.

The Amount of Fee.....£ : : is received by me,
Special..... : :
Certificate (if required) : :

Committee's Minute 29th May 1857

Character assigned Record Book of Survey

J. H. Ritchie
Thos. W. Wain

