

REPORT of SURVEY for REPAIRS.

No. 10 Survey held at London Date 25th May 1857
 on the H. J. Talbot Master D. Putt
 Tonnage 250 Built at Southampton When built 1851
 By whom built _____ Owners Newman
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Backwoods dry dock

Last Survey, No. 19558 Port London Classed 13 A 1
 53

REPAIRS

now done; the yellow metal sheathing stripped, recaulked from waterway seam to keel and the yellow metal sheathing renewed upon paper -

added five pairs of diagonal iron knees to lower deck and lodging knees in the mast rooms of the same -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson } <u>Good</u>	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches } <u>where seen</u>	Boats
Upper Deck Beams & Fastenings } <u>do</u>	Timbers of the Frame } <u>do</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>where seen</u>	Keelsons } <u>do</u>	Sails } <u>In good order</u>
Planksheers } <u>do</u>	Clamps and Shelves } <u>do</u>	Anchors No. of } <u>and</u>
Sheerstrakes } <u>do</u>	Ceiling } <u>do</u>	Cables } <u>sufficient</u>
Topsides } <u>do</u>	Rudder } <u>do</u>	Hawsers and Warps
Wales } <u>do</u>	Copper } <u>on paper</u>	Standing & Running Rigging
Plank (Bottom) and Counter } <u>do</u>	When put on } <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. new & good

This vessel is now in a good and efficient state and eligible in our opinion to remain classed.

The Amount of Fee.....£ _____ is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 19th June 1857

Character assigned 13 A 1

Thos. W. Rawlin
H. J. Boulders



© 2019

Lloyd's Register Foundation

LON 638-0310