

21383

REPORT of SURVEY for REPAIRS.

No. 46 Survey held at London Date 22nd Oct^r 185 7
on the S^{te} "Maid of Alm" Master J. Stanton
Tonnage 100 Built at Aberdeen When built 1841
By whom built _____ Owners Simpson & Co
Port belonging to Berwick Destined Voyage Lon to Alenmouth
If Surveyed Afloat or in Dry Dock S^{te} Andrews Wharf

Last Survey, No. 20787 Port London Classed 9 Tri 1
REPAIRS C-3-56

Examined this vessel (per order) for Annual Survey found the main keelson very defective left notice card for its renewal with the Master who reported his intention to forward it to the Owners and to follow with the ship on Friday morning

Present Condition of the

Decks <u>very much worn</u>	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. _____

We are of opinion this vessels character should be expunged until the above is attended to

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 23rd October 185 7

Character assigned Expunge character

Edmund Touchman
W. J. Mumford



© 2019

Lloyd's Register
Foundation

8500-1639-0058
LON 639-0058