

21660

REPORT of SURVEY for REPAIRS.

No. 776 Survey held at London Date 10th March & 8th April 1858
 on the Ship Cyphrenus Master W. Peacock
 Tonnage 633 Built at Memel When built 1852
 By whom built _____ Owners Hodgkinson &
 Port belonging to London Destined Voyage London to India
 If Surveyed Afloat or in Dry Dock St. Katharine's Docks

Mr. H. Peacock
Capt.

Survey, No. 21218 Port London Classed 7A1
36.

AIRS

Six pairs of staple standards in tween decks

This Vessel was found much infected with dry rot in the upper deck beams, shelf & waterway parts of which on being removed, showed that the defect had extended to the frame and sheerstrakes, Apron &c. -
 Notice cards were sent requesting that the defective parts be removed for the efficient repair of the ship which recommendation the Owners have declined proceeding with and have decided on repairing regardless of a Character.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The extent of the defect not having been ascertained and the Owners having determined not to proceed with the requisite repairs. We respectfully recommend that the Ship's Character be expunged from the Register Book until properly repaired.
 The Amount of Fee.....£ : : is received by me,

Special..... 2 : 2 : 0.

Certificate (if required) : :

Committee's Minute 9th April 1858

Character assigned Expunge Character

Notice to Owners
 Letter
 10 April 1858

W. S. Mumford
 J. H. Ritchie

Edmund Couchman

Lloyd's Register
 Foundation

LON639-0318