

#21718

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date 6th April 1858
on the Brig "Bradford" Master R. Ralston
Tonnage 195 Built at Hull When built _____
By whom built _____ Owners G. Maw
Port belonging to London Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock Charlton Wharf

M. G. Gelliey
Clerk

Last Survey, No. _____ Port _____ Classed _____

REPAIRS

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

A survey was called on this vessel by request of the Owner, for advice as to classing, and he declined to enter at present into the repairs recommended

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute _____ 185 _____

Character assigned _____

Mr Maw
Whitehall Place
Gravesend

J. H. Giltman
Thos. M. Maw



© 2019

Lloyd's Register
Foundation

LON 639-0368