

REPORT of SURVEY for REPAIRS.

21962

No. 362 Survey held at London Date 12th May 1858
 on the Ship "London" Master J. Young
 Tonnage 612 Built at London When built 1833
 By whom built _____ Owners Teigne & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Messrs. Fletchers Dry Dock

Last Survey, No. 21572 Port London Classed 1201. Rest 146 for 3 years
 REPAIRS and Cont. 34 for 3 years

"This vessel was Docked in order to stop a private leak in the garboard seam.

We examined the bottom and found the yellow metal sheathing much worn and perforated.

(Mr. Smith) one of the owners informed us it was their intention to lay her up for some time, but would place her in a Dry Dock, strip off the metal sheathing and make her efficient before sending her to sea."

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. M.</u> When put on <u>1854</u>	Standing & Running Rigging
Plank (Bottom) and Counter		
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

We therefore beg to recommend her remaining on her last state of Survey, as the owners requested further might be deferred for the present. Should the Committee

The Amount of Fee.....£ : : is received by me, see fit.

Special..... : :

Certificate (if required) : :

Committee's Minute 21st May 1858

Character assigned Preferred