

21855

REPORT of SURVEY for REPAIRS.

No. 576 Survey held at London Date 26th June 1858
on the Ship Bussorah Merchant Master
Tonnage 531 Built at Calcutta When built 1818
By whom built _____ Owners D. Dumbur
Port belonging to London Destined Voyage India
If Surveyed Afloat or in Dry Dock in Messrs' Jones' dry dock

Recd 12 July
1858

Last Survey, No. 21071 Port London Classed A1 SS 49
56

REPAIRS

At present the Yellow Metal has been stripped off, doubling of bottom caulked and resheathed with Yellow Metal
This vessel's time for retaining the Asterisk character having elapsed, the owner declines subjecting her to Survey at present for reclassification to which decision we beg to call the attention of the Committee

Will^m C. Davey
J. Martin.
At Sunderland 10th July/58

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The Amount of Fee.....£ : : is received by me,


Special..... : :

Certificate (if required) : :

Committee's Minute 13th July 1858
3rd August

Character assigned

Deferred
Write owner
13th July
1858



© 2019

Lloyd's Register
Foundation