

REPORT of SURVEY for REPAIRS.

21975

Recd. 10.9.58

No. 133 on the Bark "Derwent" Survey held at London Date August 30. to Sept 10 1858
 Master W. H. Harding
 Tonnage 366 Built at Sunderland When built 1835
363 Per Register
 By whom built _____ Owners Wilson & Barton
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Lincolns slip

Last Survey, No. 21148 Port London Classed S.S. / 521 * F. 1.

REPAIRS now done. Bottom sighted and metal patched, deck fore-castle, and poop deck caulked.

Present Condition of the

Decks <u>caulked</u>	Treenails _____	Windlass and Capstan <u>good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>good & sufficient</u>
Upper Deck Beams & Fastenings <u>where</u>	Timbers of the Frame <u>where</u>	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>seen</u>	Keelsons <u>seen</u>	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>3 B. 15. 11.</u>
Sheerstrakes _____	Ceiling _____	Cables <u>good & sufficient</u>
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales <u>caulked</u>	Copper <u>up. m. When put on 1856</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	On felt	
General Observations and Opinion, _____	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>	

This vessel so far as could be examined appears fit for the conveyance of dry and perishable goods, and in my opinion capable to remain as Classed * F. 1 until the end of the present year.

The Amount of Fee.....£ 1 : - : is received by me,

Special..... : - : }

Certificate (if required) : 5 : }

Committee's Minute 11. September 1858

Character assigned LD

Address 33 Clements Lane, City



© 2019 Lloyd's Register Foundation

1910-0164