

22013

REPORT of SURVEY for REPAIRS.*Change of Owners &c**Recd 28/9/58*No. *883*

Survey held at

London

Date

*Sept. 24th*185*8*

on the

Barge "Asia"

Master

J. H. Whitehead

Tonnage

523

Built at

Calcutta

When built

1875

By whom built

Owners

J. Chambers & Co

Port belonging to

London

Destined Voyage

West Indies

If Surveyed Afloat or in Dry Dock

Union Dry Dock & East London Dock

Last Survey, No.

20430

Port

London

Classed

F.A. 1S.S. 56**Clap*

REPAIRS

There was an order given for her to be surveyed for re-entry of class **F.A. 1*.

An examination found the upper deck clump on the starboard side in midships and on the larboard side forward; the apron, and the ceiling defective.

The owners declined entering into the necessary repairs for the class contemplated.

The Riding Bits have been replaced by a Windlass.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

I am of opinion, that in her present state, she is not fit for the class sought - viz - **F.A. 1*.

B. W. Maymouth

The Amount of Fee.....£ : : is received by me,

Special..... / : / :

Certificate (if required) : :

Committee's Minute

*5th October*185*8*

Character assigned

Deferred



© 2019

Lloyd's Register Foundation

LON640-0200