

ANNUAL SURVEYS.

22010

No. 871 Survey held at London Date Sept. 6th 1858
 on the Ship "Morayshire" Master J. Mathers
 Tonnage 788 Built at Moulmein When built 1833
 By whom built _____ Owners D. Dunbar
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 19953 Port of London Classed 12 A. 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame } <u>Good where</u>	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons } <u>seen -</u>	Sails } <u>sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes } <u>Butts</u>	Ceiling	Cables
Topsides } <u>Caul Red</u>	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

now done the Yellow Metal renewed on the wood sheathing.
a listing cut out of the sheathing at the wood ends, and
the wood ends caulked - She is fit to remain as classed

Committee's Minute 8th October 1858

Character assigned

12 A. 1

recd Yell

Certificate (if required)

No. 143 Survey held at London Date Sep 18th 1858
 on the Ship "Caroline Coventry" Master Freeman
 Tonnage 902 Built at Sunderland When built 1835
 By whom built _____ Owners Freeman &
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Canal Dry Dock & India Dock

Last Survey, No. 21002 Port of London Classed 13 A. 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame } <u>Good where</u>	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Keelsons } <u>seen</u>	Sails } <u>sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes } <u>Caul Red</u>	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

She is now fit in my opinion to remain as classed

Committee's Minute 8th October 1858

Character assigned

13 A. 1

recd Yell

Certificate (if required)



© 2019

Lloyd's Register Foundation

LN640-0205