

22039

REPORT of SURVEY for REPAIRS.

of Damage & Co.
 No. 803 Survey held at Londonderry Date Sep^r 21st to 24th 1858
 on the Ship "Arcturusa" Master W. Clark
 Tonnage 542 Built at Sunderland When built 1857
 By whom built _____ Owners J. Allan
 Port belonging to Londonderry Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mess^{rs} Young's Dry Dock

Last Survey, No. 1109 Port Sunderland Classed 13 A 1.

REPAIRS of damage now done. The yellow-metal stripped off the bottom, vessel caulked from keel to the waterway seams, and yellow metal renewed on floor in upper courses and bare bottom below.
Other repairs viz: Port-side house-pipe repaired and upper dove-tail plates renewed.

Present Condition of the

Decks <u>good</u>	Treenails _____	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson _____	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches _____	Boats <u>good and sufficient</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where</u>	Sails _____
Planksheers _____	Clamps and Shelves <u>seen</u>	Anchors No. of <u>3 B. 15. 16</u>
Sheerstrakes <u>caulked</u>	Ceiling _____	Cables <u>good and sufficient</u>
Topsides <u>"</u>	Rudder _____	Hawsers and Warps _____
Wales <u>"</u>	Copper <u>W. M.</u> When put on <u>now done</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>"</u>	General Observations and Opinion, <u>Caulking of Bottom, Deck, & Waterways. <u>good where tested.</u></u>	

This vessel is now in good condition, and in my opinion eligible to remain as Classed 13 A 1.

The Amount of Fee.....£ : : is received by me,

Special..... 3 : 3 : £

Certificate (if required) : : :

Committee's Minute 22nd October 1858

Character assigned 13 A 1 record Y.M.
Damage fee £3. 3^d
see also Pitches for Damage Report



© 2019

Lloyd's Register
Foundation

LON 640-0224