

22113

REPORT of SURVEY for REPAIRS.

change of owners
 No. 115 on the Y^h "Wellington" Survey held at London Date Oct 11th to 22nd 1858
 Master M. Howlett
 Tonnage 480 Built at Sunderland When built 1847
 By whom built _____ Owners ~~East & Simpson &~~
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock New Crane dry dock

Last Survey, No. 21149 Port London Classed 10-A-1
 REPAIRS Cont 57 - 3 57

Now done: Yellow metal stripped, eight fore hoods of ceiling (next keelson) on the starboard and six on the port bow new of English Oak, five strakes of ceiling next above bilge on each side from the main mast forward retreenailed with English Oak - Stecaulked from Waterway seam to keel and resheathed with Yellow Metal upon Felt -
 Foremast new

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>XM on 1'</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where tried
 This vessel is now in good condition and is eligible in my opinion to remain classed A 1

The Amount of Fee.....£ 1 : - : - is received by me,

Special..... 2 : 2 : -

Certificate (if required) : : -

Committee's Minute 10th December 1858Character assigned Cont 3 A 1

© 2019

Lloyd's Register
Foundation

LON640-0294