

REPORT of SURVEY for REPAIRS.

22164

No. 206 on the S.S. Satellite Survey held at London Date Nov 25th to Dec 6th 1858
 Master Trowsdale
 Tonnage 245 Built at Sunderland When built 1852
 By whom built _____ Owners Trowsdale
 Port belonging to Stockton Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Now Crane dry dock

No 24.12.58

Last Survey, No. 10192 Port London Classed SA 1
 33

REPAIRS

Yellow metal stripped - Fore keel renewed with English Elm - Windlass new of English oak, two deck planks next waterway of pine - Reaulked from plank sheers to keel and sheathed with yellow metal upon Felt.

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good & sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>do</u>	Timbers of the Frame	} <u>where seen</u>	Masts, Yards, &c.	} <u>Good & sufficient</u>
Lower Deck Beams & Fastenings		Keelsons		Sails	
Plank sheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} <u>where seen</u>	Ceiling	} <u>where seen</u>	Cables	} <u>where seen</u>
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>on F</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tried

This vessel appears in good condition and is eligible in my opinion to remain clasped SA 1

The Amount of Fee.....£ 10 - is received by me,

Special..... 2 : 2 -

Certificate (if required) : 5 : 0

Committee's Minute 18 January 1859

Character assigned SA 1

Thos. W. Wawn



© 2019

Lloyd's Register Foundation

LONG40-0342