

# REPORT of SURVEY for REPAIRS.

22290

No. 94 Survey held at London Date March 10<sup>th</sup> 1859  
 on the Schooner "Victor" Master Rhodes

Tonnage 82 Built at Portsmouth When built 1847  
 By whom built \_\_\_\_\_ Owners Messrs Smith &

Port belonging to London Destined Voyage \_\_\_\_\_

If Surveyed Afloat or in Dry Dock Plough Wharf Isle of Dogs

IB 08E 1st ON D 1/2 52 S 1/2 52

Last Survey, No. 1186 Port Yarmouth Classed 6 R. Clas omitt

## REPAIRS

There was an order given for this vessel to be surveyed for classification - An examination found the deck in a very decayed state, and a portion of the Ceiling defective -

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

## General Observations and Opinion,

## Caulking of Bottom, Deck, & Waterways.

The undersigned writes to the Owner recommending the defective deck and Ceiling to be renewed, and the vessel to be placed in such a position that her bottom may be examined - The Owner has declined to comply with the

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 :

Certificate (if required) : :

Committee's Minute 15<sup>th</sup> March 1859

Character assigned Expence Character

Noting to owner  
15.3.59

Above suggestions at present -  
B. W. W. W. W. W.



© 2019

Lloyd's Register Foundation  
 LONG40-0474