

22303

REPORT of SURVEY for REPAIRS.*and Change of Owners*

No. 580 on the S. "Dustyn" Survey held at London Date 18th & 19th April 1859
 Master Oppenheim
 Tonnage 803 Built at Quebec When built 1849
 By whom built W. Ray Owners W. Ray
 Port belonging to London Destined Voyage East Indies

If Surveyed Afloat or in Dry Dock Globe dry dock5 VM & pts 56 over pt TBSy pms 53- W pt V. & S. 56

Last Survey, No. 3676 Port Greenock Classed 5 Li Clap on the SS. 55-3 hrs C 2 38

REPAIRS

Wane part of stem post cut out and piece. also defects in Riber keelson amidships. three short planks of lower hold ceiling apr now renewed with Pine caulked from Yellow Metal line upwards for piece of false keel now renewed

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	<i>where</i>	Breasthooks and Stemson	<i>where</i>	Pumps	<i>Good</i>
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	<i>and</i>
Lower Deck Beams & Fastenings	<i>seen</i>	Keelsons	<i>seen</i>	Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling <i>where seen clear of lumber &c</i>		Cables	<i>sufft</i>
Topsides		Rudder <i>Yellow Metal on feet</i>	<i>Good</i>	Hawsers and Warps	
Wales <i>pt Shear on feet</i>	<i>Good</i>	Copper <i>When put on</i>	<i>1856</i>	Standing & Running Rigging	
Plank (Bottom) and Counter	<i>do</i>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. *Good where tested*

This vessel appears fit for the safe conveyance of dry cargoes and may be released at F. 1

*Will. L. Davey*The Amount of Fee.....£ 1 : - : is received by me,Special..... 1 : 1 : - *J. H.*Certificate (if required) : 5 :Committee's Minute 26th April 1859Character assigned F. 1*record repairs**M. B.*

© 2019

Lloyd's Register
Foundation

LON 641-0061