

REPORT of SURVEY for REPAIRS.

No. 535 Survey held at London Date June 28 to August 9 1859
 on the Ship "Burmah" Master J. Lloyd
 Tonnage 620 Built at Sunderland When built 1853
 By whom built _____ Owners Blair & Co
 Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Pletcher's dry dock and S^r Parkman's d^r

Last Survey, No. 20467 Port London Classed 10 A 1.

REPAIRS now done. yellow-metal stripped and vessel caulked from
keel to the waterway-seams, new fore, main, and mizen-masts
head joints repaired and yellow-metal renewed on yells.

Present Condition of the

Decks <u>good</u>	Treenails _____	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson _____	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches _____	Boats <u>good and efficient</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>3 B. 13. 1 R.</u>
Sheerstrakes <u>caulked</u>	Ceiling _____	Cables <u>one bower now new, good and complete</u>
Topsides <u>"</u>	Rudder _____	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>y. m. When put on now done on yells.</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Caulking of Bottom, Deck, & Waterways. <u>good where tested.</u>	

General Observations and Opinion,

This vessel is now in good condition and in my opinion
eligible to remain as Classed 10 A 1.

The Amount of Fee.....£ _____ is received by me,

Special..... : :


Certificate (if required) : :

Committee's Minute 26th August 1859

Character assigned 10 A 1 second (yell)

Charge for Damage £ 3 3
no repair fee

J. P. Light.
J. H. Ritchie



© 2019

Lloyd's Register
 Foundation
 LONG41-0274