

REPORT of SURVEY for REPAIRS.

22609

No. 88 Survey held at London Date August 30th 1859
 on the 43^{1/2} "Viceroy" Master W. Shaw
 Tonnage 667 Built at Wool Scotland When built 1849
 By whom built _____ Owners E. Sheldon & Co
 Port belonging to London Destined Voyage Honduras
 If Surveyed Afloat or in Dry Dock Afloat W. I. Dock
pts. 53 R & J M 53 over pt 1 B 8/7/53

Last Survey, No. 21017 Port London Classed 4 A 1 SS. 57-42
omitted

REPAIRS

Present Condition of the

Decks	} <u>Good</u>	Treenails	} _____	Windlass and Capstan	<u>good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>do</u>
Comings	} _____	Transoms, Pointers, and Crutches	} _____	Boats	<u>do</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	<u>lower mast to be new</u> <u>remains good</u>
Lower Deck Beams & Fastenings	} <u>do</u>	Keelsons <u>pt seen</u>	} <u>where seen</u>	Sails	_____
Planksheers		Clamps and Shelves		Anchors No. of	<u>good</u>
Sheerstrakes	} <u>where seen</u>	Ceiling	} _____	Cables	<u>sufficient</u>
Topsides		Rudder		Hawsers and Warps	_____
Wales	} _____	Copper <u>12 X 12</u> When put on <u>1854</u>	} _____	Standing & Running Rigging	_____
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where seen

This vessel appears in good condition and with the exception of the lower masts (fore & main) which the owner has contracted to renew I am of opinion she is eligible to

The Amount of Fee.....£ 1 : - : is received by me, be returned

Special..... 1 : 1 :

Certificate (X required) : 5 :

Committee's Minute 30th August 1859

Character assigned _____



© 2019

Lloyd's Register

LONG 41-0249