

REPORT of SURVEY for REPAIRS.

No. 18 Survey held at London Date July 2nd 1859
 on the S. X. "York" Master 14 Redpath
 Tonnage 940 Built at Sunderland When built 1854
 By whom built _____ Owners J. Allan
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 21506 Port London Classed 13A1

REPAIRS

Now done: Yellow metal stripped ship re-caulked from upper part of wales to keel and the yellow metal sheathing renewed upon three strakes of felt on the upper courses and on the bare planking below —

Present Condition of the

Decks	} good	Treenails	} Good	Windlass and Capstan	} good and
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Brutches		Boats	
Upper Deck Beams & Fastenings	} do	Timbers of the Frame	} where seen	Masts, Yards, &c.	} sufficient
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} where seen	Ceiling	} Standing & Running Rigging	Cables	}
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>1/2</u> on <u>1/2</u> When put on <u>now</u>			
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tried

This vessel is now in good condition and is eligible in my opinion to remain classed

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : -

Certificate (if required) : :

Committee's Minute 20th September 1859

Character assigned 13A1

record Y. M. L. R.



© 2019

Lloyd's Register Foundation
 LON 641-0305

22637

Recd 15.9.59