

22640

REPORT of SURVEY for REPAIRS. and change of Owners

No. 303 Survey held at London Date 24th Aug^r 1859
on the B^k "William & Jane" Master R Morris
Tonnage 489 Built at Sunderland When built 1833
By whom built 450 Owners Quart Simpson
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock in dry dock

Recd 17.9.59

Last Survey, No. 22406 Port London Classed S A 1

REPAIRS

In clearing the hull and examining parts not seen on the
last survey, ^{in June (still remaining in London)} the After Deadwood knee was found defective & now
renewed with East India hard wood and Yellow metal bolter
2 lower crutches repaired & Y^m bolter - new one & main keels

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings	} <u>good</u>	Transoms, Pointers, and Crutches	} <u>good</u>	Boats	} <u>good</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder	} <u>seen</u>	Hawsers and Warps	} <u>suff</u>
Wales		<u>Yellow metal on</u>		Standing & Running Rigging	
Plank (Bottom) and Counter	} <u>seen</u>	<u>Copper felt</u> When put on <u>1839</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where seen

She is now in good condition and eligible to remain as classed S A 1

Wm L. Daver

The Amount of Fee.....£ / : : is received by me,

Special..... : : :

Certificate (if required) : : :

Committee's Minute 20th September 1859

Character assigned S A 1



© 2019

Lloyd's Register
Foundation
LON 641-0308