

ANNUAL SURVEYS.

22733

No. 707 Survey held at London Date 13th Oct^r 1859
 on the S. "Admiral" Master - Clerk
 Tonnage 707 Built at Dumbarton When built 1830
 By whom built 784 Owners Potter & Co
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Nipam's dry dock

Last Survey, No. 21901 Port of London Classed 10 A1

The present Condition of the

Decks	} <u>where</u>	Treenails	} <u>examined</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>seen</u>	Keelsons	} <u>only</u>	Sails	} <u>and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>good</u>	<u>4th on 28</u>	} <u>decks</u>	Standing & Running Rigging	} <u>suffr</u>
Plank (Bottom) and Counter		<u>Copper</u>		When put on <u>1837</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Yellow metal patches where required and a short after piece
of false keel renewed. Examined her between decks and found all sound & firm
last seen below there being 200 tons of cargo on board not yet discharged. From her
condition where seen I am of opinion she may continue as classed 10 A1

Committee's Minute 1st November 1859 Will: L. Davey
 Character assigned 10 A1

Certificate (if required)

No. 825 Survey held at London Date 20th & 21st Oct^r 1859
 on the S. "Arctura" Master W. Clark
 Tonnage 942 Built at Sunderland When built 1837
 By whom built Owners A. Allan
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Nipam's dry dock

Last Survey, No. 22139 Port of London Classed 13 A1

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>do</u>	Keelsons	} <u>do</u>	Sails	} <u>and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>do</u>	<u>4th on 28</u>	} <u>do</u>	Standing & Running Rigging	} <u>suffr</u>
Plank (Bottom) and Counter		<u>Copper</u>		When put on <u>1838</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where tested
Yellow metal patches where required. Upper deck shelf
pieces additionally through bolts with I.M. she is now in good condition
and may continue as classed 13 A1

Committee's Minute 1st November 1859 Will: L. Davey
 Character assigned 13 A1

Certificate (if required)