

**REPORT of SURVEY for REPAIRS.**

No. 143 Survey held at London Date October 15<sup>th</sup> 1859  
 on the S<sup>c</sup> Derwentwater Master Thomson  
 Tonnage 623 Built at Sunderland When built 1852  
 By whom built \_\_\_\_\_ Owners Richardson  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Simkins dry dock

Last Survey, No. 21009 Port London Classed 12 A 1

## REPAIRS

Now done, the yellow metal sheathing stripped, the garboard strakes and butts of planks below metal line recaulked and the yellow metal sheathing renewed on three strakes of Telt in upper courses and paper below one plank on starboard buttock renewed with E. S. Teak

## Present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>In good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>do</u>	Timbers of the Frame	} <u>where seen</u>	Masts, Yards, &c.	} <u>after and</u>
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} <u>where seen</u>	Ceiling	} <u>do</u>	Cables	} <u>sufficient</u>
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>YM</u> <u>or</u> <u>pt F</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter	<u>do</u>				

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good when tried

This vessel is now in good condition and is eligible in my opinion to remain classed

The Amount of Fee.....£ : : is received by me, Robt. W. Hutton

Special..... 1 : 1 : 4

Certificate (if required) : 5 : —

Committee's Minute 4<sup>th</sup> December 1859

Character assigned 12 A 1



© 2019

Lloyd's Register  
Foundation

LON 642-0021