

REPORT of SURVEY for REPAIRS.

22880

No. 135 Survey held at London Date March 15 1859
 on the Ship Hastings Master May
 Tonnage 595 Built at Sunderland When built 1855
 By whom built _____ Owners Willis & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Sketcher's dry dock.

Last Survey, No. 21342 Port London Classed G S.I.

REPAIRS now done. - Caulked from metal over all. front of poop and forecastle altered. Quarter pieces reduced in size. Stems on added of English oak and two Iron hoops fitted over the same and bolted with metal. part of lower deck renewed and the whole caulked.

Present Condition of the

Decks <u>good and caulked</u>	Treenails _____	Windlass and Capstan <u>good</u>
Waterways <u>good</u>	Breasthooks and Stemson _____	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches _____	Boats <u>good and sufficient</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where</u>	Sails _____
Planksheers <u>"</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>caulked</u>	Ceiling _____	Cables _____
Topsides <u>"</u>	Rudder _____	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Y.M.</u> When put on <u>1857</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>good where seen</u>	Caulking of Bottom, Deck, & Waterways. <u>good where seen tested.</u>	

This vessel is now in good condition, and in my opinion eligible to remain as Classed G S.I.

The Amount of Fee.....£ 1 : : is received by me,

Special..... : : :

Certificate (if required) : 5 : -

Committee's Minute 27th January 1856

Character assigned G S.I.



© 2019

Lloyd's Register Foundation

LON 642-0102