

REPORT of SURVEY for REPAIRS.

22993

No. 274 on the 13th Wm Simpson Master J. Platt
 Survey held at London Date Jan^y 13th & 14th 1860
 Tonnage 256 Built at Sunderland When built 1849
 By whom built _____ Owners Thorntons & West
 Port belonging to London Destined Voyage Batavia
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 21681 Port London Classed 13 A 1

REPAIRS

Yellow metal stripped: fittings of head taken down
 caulked underneath and refitted. Ship recaulked
 from keel to plank sheers and the yellow metal
 sheathing renewed upon Felt.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Plank sheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>FLVM</u>	When put on <u>now</u>	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tried

This vessel appears in good condition and is
 eligible in our opinion to remain classed A 1

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 16th March 18560

Character assigned 13 A 1 record Ym

Thos. W. Hawn
W. S. Munford



© 2019

Lloyd's Register
 Foundation

LON 642-0217