

No. 155

Survey held at

London

Date

March 14 1860

on the

Ship Vincira

Master

Swanson

Tonnage

240  
1037

Built at

Swanland

When built

1857

By whom built

Owners

Ed Dunbar

Port belonging to

London

Destined Voyage

Sydney

If Surveyed Afloat or in Dry Dock

In Mess<sup>r</sup> Somers by Jack of Afloat, Chas. J. J. J.

Last Survey, No.

22586

Port of

London

Classed

13 A 15 mo 59

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plunk (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons not seen for Ballast

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors

No. of 3, 1, 1

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good when seen

She has now been by Jack<sup>c</sup> to examine Bottom, all appears to be in good condition eligible to remain as

Committee's Minute

20<sup>th</sup> March

1860

Classed

13 A 1

Character assigned

13 A 1L. D.L. D. Martin

Certificate (if required).

LON 642-0233