

23048

REPORT of SURVEY for REPAIRS.

No. 882 Survey held at London Date 23rd 25th February 1860
on the S. Art Union Master Morrison
Tonnage 758 Built at Sunderland When built 1857
By whom built _____ Owners Shepherd
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Limehouse dry dock

Last Survey, No. 6245 Port Sunderland Classed 13 A 1
57

REPAIRS

Now done; yellow metal sheathing stripped
uncaulked from keel to planksheers and the
yellow metal sheathing renewed on felt.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons	<u>Good</u>	Sails	<u>Good and</u>
Planksheers	<u>Good</u>	Clamps and Shelves	<u>where seen</u>	Anchors No. of	<u>sufficient</u>
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>L & M</u>	When put on <u>now</u>	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tried

This vessel is now in good and efficient
condition and is eligible in our opinion to remain
classed 13 A 1

The Amount of Fee.....£ : : is received by me,

Special..... : : ✓

Certificate (if required) : :

Committee's Minute 23rd March 1860

Character assigned 13 A 1

recd M. D.



© 2019

Lloyd's Register

Foundation
LON 642-0239