

# ANNUAL SURVEYS.

23042

Recd 29.3.60

No.

Survey held at

Date

1860

on the

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

2 mo 60

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. The Bottom sheathed with Yellow Metal over Felt, did not see the Caulking previously tried.

Committee's Minute

1860

Character assigned

Certificate (if required)

No.

Survey held at

Date

1860

on the

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

50

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now Docked to examine Bottom. The appears to be in good condition, eligible to remain as classed

Committee's Minute

1860

Character assigned

Certificate (if required)

LON 642-0260