

Change of Owners REPORT of SURVEY for REPAIRS.

23058

No. 37 Survey held at London Date March 12th 1860
 on the Barge "Earl of Southesk" Master Robert Ritchie
 Tonnage 336 Built at Arbroath When built 1838
 By whom built _____ Owners J. J. Pennie
 Port belonging to Aberdeen Destined Voyage _____
 If Surveyed Afloat or in Dry Dock King & Queen Dry Dock

Recd 26.3/60

Last Survey, No. 1850 Port Aberdeen Classed 10A-1
 58

REPAIRS

Now done, her chain Cables ranged, examined and found good and sufficient -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1838</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

*Good where seen
 She is fit in my opinion to remain as classed 10A-1.
 B. Maymouth*

The Amount of Fee.....£ 1 : - : - is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 13th April 1860

Character assigned MA-1



© 2019

Lloyd's Register
 Foundation

LON 642-0276