

REPORT of SURVEY for REPAIRS.

23068

No. 182 Survey held at London Date 9th 11th April 1860
 on the Brig Africamus Master Lee
 Tonnage 183 Built at Yarmouth When built 1838
 By whom built _____ Owners Gosler & Smith
 Port belonging to London Destined Voyage London Africa
 If Surveyed Afloat or in Dry Dock Scrubhouse dry dock

Recd 12/4/60

Last Survey, No. 20196 Port London Classed 12 A 1
Rest 55 - 7 - 56

REPAIRS

On visiting this vessel I found that the yellow metal sheathing was being patched and repaired, the vessel having been sheathed with yellow metal between March and May 1855. When the vessel was restored left notice card that the yellow metal sheathing having been on five years he now stripped and the bottom caulked in accordance with the rules - Section 67

I have since been informed that the metal will be stripped on her return from a voyage to the coast of Africa of two or three months duration

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>G M</u> When put on <u>1855</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The above recommendation not being complied with I beg respectfully to submit the case to the consideration of the Committee relative to retaining her character

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 17th April 1860

Character assigned Rest 7th 1860

A. S. Munro