

REPORT of SURVEY for REPAIRS.

No. 52 Survey held at London Date June 6th 1860
 on the 43^{1/2} "Navarino" Master Morgan
 Tonnage 493 Built at Cochin When built 1808
 By whom built _____ Owners G. Marshall
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Limchouse dry dock

Last Survey, No. 21836 Port London Classed * A, 1
 SS. 34 58

REPAIRS

Hung in Shores
Recarved from plank sheers to keel and the yellow metal sheathing renewed upon paper.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Tomings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>NM</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

This vessel is now in good condition "fit for the conveyance of dry and perishable cargoes to and from all parts of the world" and is eligible in our opinion to remain classed


The Amount of Fee.....£ : : is received by me,

Special..... 1: 1: 3/6

Certificate (if required) : 5: 5/0

Committee's Minute 29th June 1860

Character assigned A, 1 asterisk
record



© 2019

Lloyd's Register Foundation

LONG43-0006