

REPORT of SURVEY for REPAIRS.

23252

No. 168 Survey held at Londron Date June 21st to 25th 1860
 on the Barp Lais in a Master D. Thompson
 Tonnage 209 Built at Bidjora When built 1836
 By whom built _____ Owners Henry & Co.
 Port belonging to Londron Destined Voyage Archangel
 If Surveyed Afloat or in Dry Dock Fore & Aft Dock Ways

Last Survey, No. 15284 Port Liverpool Classed 12 S.S. / 56 *E. 1.
PTIB Supms 53 & 56 ND 57

REPAIRS now done. One hold beam forward scapled. One hold with new middle piece. And main hatch way beam to upper deck changed. Several iron pillars repaired. yellow metal patched. Wales partially caulked and made fair where chaped.

Present Condition of the

| | | |
|-----------------------------------|--|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper | Standing & Running Rigging |
| Plank (Bottom) and Counter | When put on <u>1856</u> | |
| General Observations and Opinion, | Caulking of Bottom, Deck, & Waterways. | |

This vessel is now in good condition, fit for the safe conveyance of any goods to and from all parts of the world, and in my opinion eligible to be classed *E. 1.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : J. R. Light

Certificate (if required) : 5 : -

Committee's Minute 6th July 1860

Character assigned E. 1 Asterisk

Charge for attendance £ 1. 1



© 2019

Lloyd's Register Foundation

lov643-00 24