

REPORT of SURVEY for REPAIRS.

23283

No. 150 Survey held at London Date 18th to 20th June 1860
 on the S. "Whirlwind" Master E. Edgell
 Tonnage 1003 Built at Dundee When built 1854
 By whom built _____ Owners Jones Bros
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Mr Jones' dry dock

Recd 9/7/60

Last Survey, No. 21189 Port London Classed 9.21
 57

REPAIRS

Yellow metal stripped off, recaulked from keel to metal line and re-sheathed with Yellow metal on feet new caulking tested and found good

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings	<i>Good</i>	Transoms, Pointers, and Crutches	<i>Good</i>	Boats	<i>In good</i>
Upper Deck Beams & Fastenings		Timbers of the Frame	<i>where</i>	Masts, Yards, &c.	<i>order &</i>
Lower Deck Beams & Fastenings	<i>where</i>	Keelsons		Sails	
Plank-sheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling <i>where seen clean of kentledge</i>	<i>seen</i>	Cables	<i>supp</i>
Topsides		Rudder		Hausers and Warps	
Wales	<i>seen</i>	Copper <i>1/4 in x 1/2 in</i> When put on <i>June 60</i>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where tested
This ship appears at present in good condition and eligible in my opinion to continue as classed A1

Will m C. P. Davey

The Amount of Fee.....£ : : is received by me,

Special *Caulk* 1 : 1 : -

Certificate (if required) : :

Committee's Minute 17th July 1860

Character assigned 9.21

record M



© 2019

Lloyd's Register Foundation

LON 643-0053