

# REPORT of SURVEY for REPAIRS.

23315

*Change of owners*

No. 111 Survey held at London Date 6<sup>th</sup> July 1860  
on the B<sup>4</sup> "Eden" Master R. Parsons  
Tonnage 523 Built at London When built 1826  
By whom built \_\_\_\_\_ Owners Amurthwaite X  
Port belonging to London Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock Afloat off Deptford

Last Survey, No. 961 Port Milford Classed A, 1

## REPAIRS

At the request of the owner examined her while lying Afloat in the River & found 2 poop rough tree timbers on the port side broken and one loose, also one broken on the Starboard side, lower deck hook defective under bow port post Hawse pipe worn nearly through. Caulking of main deck forward and of Waterways there very inefficient - left written recommendations for the above defects to be made good, the long boat overhauled and repaired & the chain cables hauled up for examination which has been declined

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

## General Observations and Opinion,

## Caulking of Bottom, Deck, & Waterways.

Until the above recommendations are complied with I am of opinion she is not eligible to continue as Classed A, 1

The Amount of Fee.....£..... is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 27<sup>th</sup> July 1860

Character assigned Expunge character

Notice to Owner  
27.7.60



© 2019

Lloyd's Register  
Foundation

LON 643-0086