

23333

REPORT of SURVEY for REPAIRS.

No. 58 Survey held at London Date 6th June 18 60
on the 3rd Earl Bird Master _____
Tonnage 349 Built at Littlehampton When built 1852
By whom built _____ Owners Jas. Shepherd
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Union dry dock

Rev 24/7/60

Last Survey, No. 21471 Port London Classed 13A1
REPAIRS

Three Iron hooks (the lower) forward broken at the throat repaired refitted and bolted, the ship recaulked from keel to metal line and the yellow metal renewed upon felt

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>T & Y M</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good and efficient condition and is eligible in our opinion to remain classed

13A1

The Amount of Fee.....£ : : is received by me,

Special..... 1: 1: c

Certificate (if required) : :

Committee's Minute 3rd August 18 60

Character assigned 13A1

J. W. Wainwright
W. S. Mumford



© 2019

Lloyd's Register
Foundation

LON 643-0103