

23458

REPORT of SURVEY for REPAIRS.

No. ¹⁵² Survey held at London Date July 13th 1860
on the S. George Washington Master W. Dempster
Tonnage 414 Built at Aberdeen When built 1857
By whom built _____ Owners S. Wright
Port belonging to Aberdeen Destined Voyage China
If Surveyed Afloat or in Dry Dock Princes dry dock

Recd 21/7/60

Last Survey, No. 22768 Port London Classed A 1
39

REPAIRS

one breast hook re bolted with iron.
yellow metal stripped, recaulked from keel to metal
line and the yellow metal renewed upon Felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>F&M</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tried

This vessel is now in good condition and is eligible
in our opinion to remain classed A 1

The Amount of Fee.....£ : : is received by me,
Special..... 1 : 1 :
Certificate (if required) : 5 : }

Wm. W. Wain
W. S. Thompson

Committee's Minute 2nd October 1860
Character assigned A 1
accord W. W. Wain

