

REPORT of SURVEY for REPAIRS.

No. 183 Survey held at London Date Sept^r 26th Oct^r 1860
 on the Ship "Castle Eden" Master none appointed
 Tonnage 760 Built at Sunderland When built 1842
 By whom built --- Owners Somes Bros
 Port belonging to London Destined Voyage ---

If Surveyed Afloat or in Dry Dock Somes' Dry Dock & Mr. J. Dock.

Last Survey, No. 2119th Port London Classed Res^t 155 for 6 yrs.

REPAIRS now done. The hull seam amidships stripped, hung in shores and caulked in way of the same. Lower-deck hatch renewed of English Oak. Foremost pieces of lower-deck waterway and short-pieces of ceiling over A & on each side renewed of Teak. Upper works caulked, pillaring strake between the fore and main hatchway on hold-beams renewed of Teak. New bowsprit and tizen mast, fore and main-masts shortened, and yellow-metal patched.

Please see Owner's account of repairs done in India (caused by being wormed) viz: - Fore and after pieces of hull, some planks of bottom, yellow-metal renewed &c.

Present Condition of the

Decks <u>good</u>	Treenails <u>---</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>---</u>	Pumps <u>"</u>
Rings <u>"</u>	Transoms, Pointers, and Crutches <u>---</u>	Boats <u>good & sufficient</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where seen</u>	Sails <u>---</u>
Plank-sheers <u>"</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>---</u>
Sheerstrakes <u>"</u>	Ceiling <u>---</u>	Cables <u>---</u>
Opsoides <u>"</u>	Rudder <u>---</u>	Hawsers and Warps <u>---</u>
Rails <u>"</u>	Copper <u>Y. M.</u> When put on <u>Done in India</u>	Standing & Running Rigging <u>---</u>
Plank (Bottom) and Counter <u>"</u>	Caulking of Bottom, Deck, & Waterways. <u>good where seen,</u>	

General Observations and Opinion,

This vessel is now in good condition, and in my opinion eligible to remain as Classed 155.

The Amount of Fee.....£ 2 : : is received by me, J. T. P. Light

Special..... : :

Certificate (if required) : :

Committee's Minute 13th November 1860

Character assigned Best 1st

Charge repair fee record repairs



© 2019

Lloyd's Register Foundation

LOW643-0293