

23580

# REPORT of SURVEY for REPAIRS. and Change of owners

No. 241 Survey held at London Date 3<sup>rd</sup> to 20<sup>th</sup> Nov<sup>r</sup> 1860  
on the S. "Will<sup>m</sup> Hammon" Master R. More  
Tonnage 595 Built at Sunderland When built 1853  
By whom built 683 Owners A. G. Robinson  
Port belonging to London Destined Voyage Jamaica  
If Surveyed Afloat or in Dry Dock Nelson dry dock

Nov 24. 11.60

Last Survey, No. 21782 Port London Classed 13 A1

## REPAIRS

Metal stripped from keel seams. the ship hung in shores  
and the keel seam recaulked. the metal there renewed  
recaulked from Yellow Metal line to gunwale  
new Fore & Main Masts, Bowspit, Fore Topmast & Fore top-  
sail Yard  
a Bower Anchor now supplied to make good deficiencies

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2 of Sea</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>pt new</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>do</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>3 B. 1 S &amp; 1 K</u>
Sheerstrakes	Ceiling	Cables <u>complete</u>
Topsides	Rudder	Hawsers and Warps <u>3 No (1 new) good</u>
Wales	Copper <u>Yn &amp; A</u> When put on <u>1850</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter		

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good condition and in  
my opinion eligible to continue as Classed A1

Will<sup>m</sup> C. Daves

The Amount of Fee.....£ 1 : : is received by me,

Special Caulk<sup>r</sup> 1 : 1 :  
Attendance  
Certificate (if required) : 5 :

Committee's Minute 31<sup>st</sup> November 1860

Character assigned 13 A1



© 2019

Lloyd's Register  
Foundation

LN 643-0325