

\*23645

# REPORT of SURVEY for REPAIRS.

Part 1.61  
Cont

No. 107 Survey held at London Date Dec 13<sup>th</sup> to 26<sup>th</sup> 18 60  
 on the Ship "New Era" Master J. Rhinds  
 Tonnage 725 Built at Sunderlands When built 1854  
 By whom built \_\_\_\_\_ Owners Wright & Co  
 Port belonging to Shields Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Union Dry Dock - S. J. Dock -

Last Survey, No. 22861 Port London Classed 13A.1.

REPAIRS Now done, the Apron renewed with Teak, the Stimson  
Knee with English Oak, the three lower Iron  
hooks taken down, refitted and bolted, the fore wood  
ends and the whole of the outside planking from  
the Yellow Metal sheathing to the Gunwale - Caulked -

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where</u>	Breasthooks and Stimson	Pumps
Comings } <u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame } <u>Good where</u>	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Keelsons } <u>seen</u>	Sails } <u>Sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides } <u>Caulked</u>	Rudder } <u>Iron Metal</u>	Hawsers and Warps
Wales	Copper } <u>When put on 1859</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where seen  
She is now fit in my opinion to remain as classed  
13A.1.

P. W. Wainwright

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 1/1

Certificate (if required) : :

Committee's Minute 15<sup>th</sup> January 18 61

Character assigned 13A Wainwright



© 2019  
 Lloyd's Register  
 Foundation  
 LON 643 - 0 401