

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date 28th July to 3rd Aug 1858
 on the 13th Charlotte of Derby Master W. Brooks
 Tonnage 387 Built at Sunderland When built 1852
 By whom built 421 Owners J. Ward
 Port belonging to Hull Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Bilbe's dry Dock

Recd. 6. 7. 58

Last Survey, No. _____ Port _____ Classed 8 A 1

REPAIRS

One plank of Port Topsides of East India Seat, Rider
 Keelson of East India Seat and through bolts at alternate
 Planks with the Yellow Metal, recaulked from Yellow Metal
 line to Gunwale, caulking afterwards nice and found
 satisfactory — new Fore Mast — Yellow Metal patches
 where required but without removal of old metal

Present Condition of the

Decks	<u>Good</u>	Treenails		Windlass and Capstan	
Waterways	<u>do</u>	Breasthooks and Stemson	} <u>Good</u>	Pumps	} <u>In good</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame	} <u>where</u>	Masts, Yards, &c.	} <u>order and</u>
Lower Deck Beams & Fastenings	<u>Firm</u>	Keelsons		Sails	
Planksheers	} <u>Good</u>	Clamps and Shelves	} <u>seen</u>	Anchors No. of	} <u>sufficient</u>
Sheerstrakes		<u>where</u>		Ceiling	
Topsides	<u>where</u>	Rudder		Hawsers and Warps	
Wales	<u>seen</u>	Yellow Metal on Keel	<u>1857</u>	Standing & Running Rigging	
Plank (Bottom) and Counter		Copper			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This vessel appears at present to be in good condition and I am therefore of opinion she may continue as classed 8 A 1

Willm. B. Davy

The Amount of Fee.....£ _____ is received by me,

Special..... / : / : -

Certificate (if required) : :

Committee's Minute 26th March 1858

Character assigned See annexed Survey



© 2021

Lloyd's Register
Foundation

LON644-0088