

23880

REPORT of SURVEY for REPAIRS.

No. 473 Survey held at London Date April 17th 1861
on the Amarausk Master Ransom
Tonnage 370 Built at Sunderland When built 1846
By whom built _____ Owners J Walker
Port belonging to London Destined Voyage Capu
If Surveyed Afloat or in Dry Dock New Crane dry dock & off Deptford

Last Survey, No. 23108 Port London Classed _____

REPAIRS

Rest 54 - 05 A /
Cont 59 - 2 60

Recaulked from metal line to planksheers.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame	<u>Good</u>	Masts, Yards, &c.	<u>Good and</u>
Lower Deck Beams & Fastenings	<u>where seen</u>	Keelsons	<u>where seen</u>	Sails	<u>Sufficient</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>P & Y M</u> When put on <u>1859</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good and efficient condition and is eligible in my opinion to remain classed A

The Amount of Fee.....£ : : is received by me, Thos. W. Wain
Special..... : 10: :
Certificate (if required) : 5: :
Caroline Wain

Committee's Minute 19th April 1861
Character assigned Cont 2 A

